

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2025		Claim number		Code / Agency				Date accident 12/05/2025									
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT									
Date assignment 12/05/2025		Date first survey 14/05/2025		Place MILANO		C/O RIP		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate									
Lessee / Co-owner												Date of overhaul									
Vehicle (Brand - Model - Version) TOYOTA COROLLA TS								Plate GC374YS		Vin Chassis SB1Z93BEX0E148008				First Registration 19/10/2020							
Usage status NON CONOSCIUTO		Km 176107		Tyres % 50		Color BLU		Type of enamel METALLIZED/DOUBLE		Consistency of damage YES		Type of Expert's report NOT DEFINITIVE									
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare.Q 0		Wheelbase								Seats No. 0		Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations										SR		LA		VE		ME		D.M. S.C.		Costs of spare parts (VAT excluded)	
										Dif Time		Dif Time		Dif Time		Time					
1	5610102Q01	Windshield						S		S		S									
1	52119F2907	Front bumper						S		S		S									
1	8148102A21	Front bumper side lower trim				R		S		S		S									
1	Codice Ricambio	Rettifica n.4 cerchi in lega						S		S		S									
1	Codice Ricambio	Kit incollaggio						S		S		S									
1	5330102380	Front bonnet						L		L		L									
1	75852YY900	Door sill trim				L		L		L		L									
1	75851YY902	Door sill trim				R		L		L		L									
1	6700202540	Front door				L		L		L		L									
1	6700402540	Rear door				L		L		L		L									
1	6160202530	rear mudguard				L		L		L		L									
1	521590Z949	Rear bumper						L		L		L									
1	879150238020	External rear-view mirror cap				R		L		L		L									
1	Codice Ricambio	Igienizzazione tessuto																			
1	Codice Ricambio	Fanalino retrovisore est. PRM				R															

New for old value (N)	Remarks PNEUM. GOODYEAR M+S 205/55 R16 (ANT. E POST. 4MM).
-----------------------	--